



CLUTCHTECH



TSB - N104

Worn Clutch Fork.

Applies to ClutchPro kits;

KNI28001, KNI28002, KNI28005, KNI28006, KNI28009.

The clutch fork and pivot ball in this model vehicle is prone to wear.

Areas to inspect include;

- Where the clutch fork sits on the pivot ball.
- Where the bearing carrier pivots on the clutch fork.

If any wear is evident, the clutch fork must be replaced.

LEADING BRANDS

CLUTCHPRO CLUTCHPRO
COMMERCIAL



australianclutch.com.au

1800 CLUTCH (258824)